




Environmental Management Services Company
1413 West 57th Street
Loveland, CO 80538
(970) 461-0571 * FAX (970) 461-0591

M/49/009

April 10, 2000

Mr. Tom Munson
Division of Oil Gas and Mining
1584 West North Temple, Suite 1210
Salt Lake City, UT 84114-5801

Re: Recent Conversations re file No. M/049/009



Dear Tom;

This letter is written in response to our recent conversations regarding the transfer of file No. M/049/009 Large Mining Operation Operating Permit and Reclamation Contract to Tintic Utah Metals, LLC. Specifically requested was a map clearly showing the areas proposed for disturbance, a listing of the location permitted disturbance, and a summary table listing Permit Acres, Bonded Disturbance Acres, and Actual Acres Disturbed. Enclosed please find one copy of the Eureka 7.5 minute quad showing the approximate location of permitted disturbance. The legal descriptions of the Permit Areas are listed on Table 1 and the permitted acres, bonded disturbance acres and actual disturbed acres is listed on Table 2. Also listed on the tables is the date that DOGM recognized the disturbance.

Thank you in advance for your cooperation. If I can answer any questions or provide further information, please feel free to contact me.

Sincerely,

Tom

Thomas E. Gast
Principal

Encl.: Map
Cc: Paul Spor

Tom - Original & map in MAIL
Tom

Attachment "A"

Tintic Utah Metals LLCBurgin MineOperatorMine NameM / 049/009Utah County, UtahPermit Number

The legal description of lands to be disturbed based on the 1985 Reclamation Contract is:

Facility	1/4	1/4	Sec.	T	R
Orig. Permit, 1986					
Apex No. 2	SE	NW	22	10S	2W
Hunter Shaft	SE	SW	15	10S	2W
Burgin Complex	SE	SE	15	10S	2W
Tailings Disposal	NW	NE	14	10S	2W
Settling Ponds		NE	18	10S	1W
Tot. 1986 Approval					
06/12/85 Approval					
Ponds 2,3 &4	SE	SE	15	10S	2W
12/8/1986 Approval					
Ponds A, B, C	NE	SE	15	10S	2W
12/9/1992 Approval					
Zuma Clay Pit	SE	NW	21	10S	2W

The acreage based on the 1985 Reclamation Contract is:

Facility	Permit ac.	Bonded Disturbance	Actual Disturbance
Orig. Permit, 1986			
Apex No. 2	2.8	2.8	2.8
Hunter Shaft	10.0	7.8	0.0
Burgin Complex	57.9	29.4	29.4
Tailings Disposal	49.8	28.7	0.0
Settling Ponds	180.0	36.1	0.0
Tot. 1986 Approval	300.5	104.8	32.2
06/12/85 Approval			
Ponds 2,3 &4	3.0	0.0	2.2
12/8/1986 Approval			
Ponds A, B, C	28.7	10.1	0.0
12/9/1992 Approval			
Zuma Clay Pit	7.0	5.0	5.0
Totals	379.9	119.9	39.4